MAGELLAN®

PROFESSIONAL

Firmware Release Notes	GIS

November 5, 2008

Scope

The new MobileMapper CX firmware (eBoot) version 2.5 is released.

Resolved Problems

- **FNC 183 – MobileMapper CX does not boot up (freeze after boot screen).**

Some recent MobileMapper CX units may not boot up (even if they worked well before). They freeze at the MobileMapper CX boot screen; the bar at the bottom of the screen makes it's way across the screen and then the system locks. It is impossible to restart the unit even in the rescue mode. It seems that it may happen when the battery becomes empty.

Upgrade procedure

- Copy Magellan-ebootloader.exe and Ebbot250.nbX on an SD card
- Insert the SD card into MobileMapper CX unit
- Double-click on « My Computer » icon

- Browse "SD Card" until the folder where magellan_ebootloader.exe is located
- Double-click magellan_ebootloader.exe

- Click on Update Bootloader
- Validate with "OK"
- Click on "SD card"
- Browse "SD Card" until the folder EBOOT250.nbX is located
- Select the EBOOT250 file

- When EBOOT250 is selected, click on "OK"
- Confirm the operation, click "OK"

- When "OS loadind Success" is displayed, acknowledge with "OK"
- Power off the device

- Click "OK"
- Power ON again
- Check new EBOOT version with \Windows\MagellanSystemInfo