

RELEASE NOTES

Trimble® Precision GNSS OEM Receivers, 4.94

This document contains late-breaking product information, updates, and troubleshooting tips not covered in the Trimble® OEM GNSS receivers' documentation.

- [Introduction](#)
- [Upgrade Procedure](#)
- [New Features and Changes](#)
- [Legal Notices](#)

Introduction

These Release Notes describe improvements made since version 4.93 to the following Trimble GNSS OEM receivers:

- BD910
- BD920
- BD920-W3G
- BD930
- BD960
- BD970
- BD982
- BX960
- BX982

With this release, all the above receivers can use version 4.94 firmware. To use firmware version 4.94, you must have a valid firmware warranty. You can check the Firmware Warranty Date using the web interface. Make sure the date shown is 1 May 2014 or later. Alternatively, obtain the warranty date from the WinFlash software. Select *Verify receiver options* and ensure the *Firmware Option* is 1 May 2014 or later.

For further support information, go to www.trimble.com/OEM_ReceiverHelp.

Upgrade Procedure

There are two ways to load the new firmware:

- Use the WinFlash utility (BD9xx WinFlash v234_v494.zip) downloaded from the Trimble website.
- Use the web interface of the receiver to load the firmware image file downloaded from the Trimble website.

New Features and Changes

The following improvements have been made to the OEM GNSS receivers:

General

- Number of NTRIP clients increased from one to three.
- GLONASS signal tracking improvements on BD920 and BD930
- Use of Scrambled CMR messages was broken in firmware versions 4.91 and 4.93. This issue is now fixed.
- Fixed issue of the BD982 receiver dropping some output messages while in 50 Hz Heading mode.

Documentation updates

The latest documentation can be found online at www.trimble.com/OEM_ReceiverHelp.

Legal Notices

Trimble Navigation Limited
Engineering and Construction
5475 Kellenburger Road
Dayton, Ohio 45424-1099
USA

800-538-7800 (toll free in USA)
+1-937-245-5600 Phone
+1-937-233-9004 Fax
www.trimble.com

Copyright and Trademarks

© 2015, Trimble Navigation Limited. All rights reserved.

Trimble, and the Globe & Triangle logo are trademarks of Trimble Navigation Limited, registered in the United States and in other countries. All other trademarks are the property of their respective owners.

Release Notice

This is the March 2015 release (Revision A) of the *Release Notes*. It applies to version 4.94 of the OEM GNSS receivers software.