



Trimble GNSS OEM

RECEIVERS

This document contains late-breaking product information, updates, and troubleshooting tips not covered in the Trimble® GNSS OEM receivers' documentation.

- ▶ Introduction
- ▶ Upgrade Procedure
- ▶ New Features and Changes
- ▶ Legal Notices

Introduction

These Release Notes describe improvements made since version 5.37 to the following Trimble GNSS OEM receivers:

- BD930
- BD935-INS
- BX935-INS
- BD940
- BD940-INS
- BX940
- BD970
- BD982
- BX982
- BD992
- BD992-INS
- BX992

To use the new firmware, you must have a valid firmware warranty. You can check the Firmware Warranty Date using the web interface. Make sure the date shown is 1 November 2018 or later. Alternatively, obtain the warranty date from the WinFlash software. Select **Verify receiver options** and ensure the **Firmware Option** is 1 November 2018.

For further support information, go to https://www.trimble.com/support/support_az.aspx#B. Select your BD/BX receiver and click **Support**.

Version 5.41

Revision A

May 2019

Upgrade Procedure

There are two ways to load the new firmware:

- Use the WinFlash utility (BD9xx WinFlash v54X.zip) downloaded from the Trimble website.
- Use the web interface of the receiver to load the firmware image file downloaded from the Trimble website.

New Features and Changes

The following improvements have been made to the Trimble GNSS OEM receivers.

New features and changes between 5.37 and 5.40

- Improvements to NMEA 2000 outputs.
- Improved jamming immunity on RTX signal.
- Added sCMRx support for Moving base.
- Temperature now logged if logging is enabled for diagnostic analysis.

New features and changes between 5.40 and 5.41

- Implementation of QZSS LS/SLAS correction service
- OmniSTAR® updates for beam change
- Continued improvements to BeiDou III implementation
- Improvements for GPS III satellites
- RTX updates for beam changes

Documentation updates

The latest documentation can be found online at https://www.trimble.com/support/support_az.aspx#B. Select your BD/BX receiver and click **Support**.

Legal Notices

Trimble Inc.
Engineering and Construction
5475 Kellenburger Road
Dayton, Ohio 45424-1099
USA

800-538-7800 (toll free in USA)
+1-937-245-5600 Phone
+1-937-233-9004 Fax
www.trimble.com

Copyright and Trademarks

© 2019, Trimble Inc. All rights reserved.

Trimble, the Globe & Triangle logo, and OmniSTAR are trademarks of Trimble Inc., registered in the United States and in other countries. All other trademarks are the property of their respective owners.

Release Notice

This is the May 2019 release (Revision A) of the GNSS OEM Receivers' Release Notes. It applies to version 5.41 of the Trimble GNSS OEM receivers.