# Trimble GNSS OEM

## **RECEIVERS**

This document contains late-breaking product information, updates, and troubleshooting tips not covered in the Trimble® GNSS OEM receivers' documentation.

- Introduction
- Upgrade Procedure
- New Features and Changes
- Legal Notices

#### Introduction

These Release Notes describe improvements made since version 5.46 to the following Trimble GNSS OEM receivers:

- BD940
- BD940-INS
- BX940
- BD970
- BD982
- BX982
- BD992
- BD992-INS
- BX992

To use the new firmware, you must have a valid firmware warranty. You can check the Firmware Warranty Date using the web interface. Make sure the date shown is 1 November 2018 or later. Alternatively, obtain the warranty date from the WinFlash software. Select **Verify receiver options** and ensure the **Firmware Option** is 1 November 2018.

For further support information, go to https://www.trimble.com/support/support\_az.aspx#B. Select your BD/BX receiver and click **Support**.

Version 5.48 Revision B

October 2020



#### **Upgrade Procedure**

There are two ways to load the new firmware:

- Use the WinFlash utility (BD9xx WinFlash v548.exe) downloaded from the Trimble website.
- Use the web interface of the receiver to load the firmware image file downloaded from the Trimble website.

## **New Features and Changes**

The following improvements have been made to the Trimble GNSS OEM receivers.

- Updates to NMEA 2000 message outputs.
- The Trimble AV16 antenna is now supported.
- Improvements to QZSS SLAS and MSAS positioning.
- Fixed BD940 occasional incorrect temperature display issue.
- Fixed issue with setting RTK Propagation Limit.
- Improvements to atmospheric models used in autonomous and SBAS positions.
- Added positioning averaging to BD990 reference station setup on the web interface
- Fixed an issue where certain BD990 receivers failed to boot at cold temperatures.

## **Documentation updates**

The latest documentation can be found online at https://www.trimble.com/support/support\_az.aspx#B. Select your BD/BX receiver and click Support.

## **Legal Notices**

Trimble Inc. **Engineering and Construction** 5475 Kellenburger Road Dayton, Ohio 45424-1099 USA

800-538-7800 (toll free in USA) +1-937-245-5600 Phone +1-937-233-9004 Fax www.trimble.com

#### Copyright and Trademarks

© 2020, Trimble Inc. All rights reserved.

Trimble, and the Globe & Triangle logo are trademarks of Trimble Inc., registered in the United States and in other countries. All other trademarks are the property of their respective owners.

#### Release Notice

This is the October 2020 release (Revision B) of the GNSS OEM Receivers' Release Notes. It applies to version 5.48 of the Trimble GNSS OEM receivers.