

## CHC X91+ Firmware V8.35 Release Note

### New functions

- 1.Optimize Novatel OEM board working performance.
- 2.Support CHC Tx/Rx radio.
- 3.Support collect Galileo raw data and support RTCM3.2 MSM.
- 4.Enable E5-A E5-B.
- 5.Satel radio internal com baud rate change to 38400, optimized correction delay.
- 6.Optimize Correction Latency with X-series receiver.
- 7.Support enable all satellites tracking with Hcconfig V1.1.0.1243(GPS L5 is not supported yet, user can enable through BD970 web UI).

### Fixed bugs

- 1.Fix getting source table will restart the receiver issue.

