DIP_Cap

2021

October 23, 2021   Build 5019

Changed output que from 300 to 1000 slots. The CHC receiver writes Many-Very-Short packets and overflowed 300.

The Server and Client methods now work.

2022

January 30, 2022   Build 5020

Enhanced the Timeout function to report TCP Server mode data interruptions. This was done to enumerate Starlink satellite down time.