CHCNAV

[2025] No.0012 | Release Notes

Issued: April 29, 2025

Subject: i93 Firmware 1.3.8.2

Region: International

1. Requirements

This firmware version includes fixes and enhancements to the i93 series GNSS receiver firmware.

Note: Upgrading from the previous firmware version 1.3.7 of the i93 series GNSS receiver to version 1.3.8.2 is recommended.

2. Supported GNSS Receivers

The following table identifies the GNSS receivers supported by this revision:

Part Number	Description
A11611980901070507	I93 GNSS

3. Version 1.3.8.2 Release Note

The release note describes the new features, improvements and bug fixed for the i93 series GNSS receiver firmware.

Optimize	Description	Type
Screen display	Updated compatibility with new screens.	Improvements

Note: Before updating the receiver, any files and data on the receiver must be backed up.

4. Loading the new Firmware

The new firmware can be download at:

https://chcnavigation.jianguoyun.com/p/DWJ5WmcQtq_UCxjLlfgFIAA

Note: Follow the firmware update instructions provided by CHC Navigation.

5. Additional Information

For more information about this change, please contact support@chcnav.com
CHC Navigation Support Team