

[2024] No.005 | Release Notes

Issued: July 29, 2024

Subject: i76 Firmware 1.1.9.3

Region: International

1. Requirements

This firmware version includes fixes and enhancements to the i76 series GNSS receiver firmware.

2. Supported GNSS Receivers

The following table identify the GNSS receivers supported by this revision:

Part Number	Description
A11356980005070507	i76 GNSS

3. Version 2.4.4 Release Note

The release note describes the new features, improvements and bug fixes for the i76 series GNSS receiver firmware.

Optimize	Description	Type
Set webpage	Optimise set interface display.	Improvements

Note: Before updating the receiver, any files and data on the receiver must be backed up.

4. Loading the new Firmware

The new firmware can be download at: https://chcnavigation.jianguoyun.com/p/DYjs1PUQtg_UCxi2xs4FIAA

Note: Follow the firmware update instructions provided by CHC Navigation.

5. Additional Information

For more information about this change, please contact support@chcnav.com

CHC Navigation Support Team