

# [2025] No.0013 | Release Notes

**Issued:** April 29, 2025

**Subject:** i83 Firmware 1.3.11.1

**Region:** International

## 1. Requirements

This firmware version includes fixes and enhancements to the i83 series GNSS receiver firmware.

**Note:** Upgrading from the previous firmware version 1.3.10 of the i83 series GNSS receiver to version 1.3.11.1 is recommended.

## 2. Supported GNSS Receivers

The following table identifies the GNSS receivers supported by this revision:

Part Number	Description
A19318980901070002	i83 GNSS

## 3. Version 1.3.11.1 Release Note

The release note describes the new features, improvements and bug fixed for the i83 series GNSS receiver firmware.

Optimize	Description	Type
Screen display	Updated compatibility with new screens.	Improvements

**Note:** Before updating the receiver, any files and data on the receiver must be backed up.

## 4. Loading the new Firmware

The new firmware can be download at:

[https://chcnavigation.jianguoyun.com/p/DX3\\_NiQQtq\\_UCxjVlfgFIAA](https://chcnavigation.jianguoyun.com/p/DX3_NiQQtq_UCxjVlfgFIAA)

**Note:** Follow the firmware update instructions provided by CHC Navigation.

## 5. Additional Information

For more information about this change, please contact [support@chcnav.com](mailto:support@chcnav.com)  
CHC Navigation Support Team